

360° Car Inspection Report

Professional Vehicle Assessment



Report ID: 46b59250

Date: 2026-08-27

Inspector: N. SAI KUMAR



BUY

Exterior

100

Interior

100

Engine

100

Electrical

100

Road Test

100

EXTERIOR INSPECTION

100/100

EXTERIOR — FRONT



car front view photo

Component	Condition	Status
-----------	-----------	--------

Bonnet

Good



bonnet



bonnet



bonnet



bonnet

Lh Apron

Good



lh apron

Rh Apron

Good



rh apron

Fire Wall

Good



fire wall

Windshield

Good



windshield

Front Bumper

Good



front bumper

Front Grille

Good



front grille

Lh Leg Member


Good



lh leg member

Rh Leg Member

Good



rh leg member

Lower Cross Member

Good



lower cross member

Upper Cross Member

Good



upper cross member

EXTERIOR — LEFT SIDE



car left view photo

Component	Condition	Status
Fender	Good	



fender



fender



fender



a pillar




a pillar



a pillar



b pillar



b pillar



b pillar



c pillar



c pillar



c pillar



rear door



rear door



rear door



rear door

Front Door

Good



front door



front door



front door



front door

Rear Tyre

80%-100%



rear tyre



rear tyre

Spare Tyre

80%-100%



spare tyre



spare tyre

Orvm Mirror

Good



orvm mirror



quarter panel



quarter panel



quarter panel



running board



running board

EXTERIOR — REAR



car rear view photo



dicky open photo

Component	Condition	Status
Boot Floor	Good	



boot floor

Dicky Door

Good



dicky door



dicky door



dicky door



dicky door

Rear Glass

Good



rear glass



rear glass



spare tyre



rear bumper



rear bumper



rear bumper



rear bumper



rear bumper

Tail Light Lh

Good



tail light lh

Tail Light Rh

Good



tail light rh

EXTERIOR — RIGHT SIDE



car right view photo

Component	Condition	Status
Fender	Good	



fender



fender



fender



a pillar



a pillar



a pillar



b pillar



b pillar



b pillar



c pillar



c pillar



c pillar

Rear Door

Good



rear door



rear door



rear door



rear door

Rear Tyre

80%-100%



rear tyre



rear tyre

Front Door

Good



front door



front door



front door



front door

Front Tyre

80%-100%



front tyre



front tyre



orvm mirror



quarter panel



quarter panel



quarter panel



running board



running board



PAINT THICKNESS

Panel	Microns	Assessment
Hood	N/A	-
Roof	N/A	-
Photos	N/A	-
Boot Lid	N/A	-
Rear Bumper	N/A	-
Front Bumper	N/A	-
Lh Rear Door	N/A	-
Rh Rear Door	N/A	-
Lh Front Door	N/A	-
Rh Front Door	N/A	-

UNDERBODY

Component	Condition	Status
Chassis	Good	



chassis



chassis



chassis



floor pan



floor pan



fuel tank



fuel tank



fuel tank



fuel tank



fuel tank

INTERIOR INSPECTION

100/100


INTERIOR



dashboard photo



dashboard photo



dashboard photo



dashboard photo

Component	Condition	Status
Ac Smell	Normal	●
Speakers	Working	●

Sun Roof

Good



sun roof



sun roof

Dashboard

Good



Gear Knob

Good



gear knob

Handbrake

Working



handbrake



ac cooling



door trims



door trims



door trims



door trims

Rear Seats

Good



rear seats



rear seats



rear seats

Driver Seat

Good



driver seat



driver seat

Roof Lining

Good



roof lining



roof lining



roof lining

Infotainment

Working



infotainment



infotainment

Passenger Seat

Good



passenger seat



passenger seat



passenger seat

Reverse Camera

Working



reverse camera

Steering Wheel

Good

Warning Lights

Yes



instrument cluster



instrument cluster

ENGINE INSPECTION

100/100


MOTOR & BATTERY




motor photo



motor photo



motor photo



motor photo

Component	Condition	Status
Charging Port	Good	



charging port


Battery Health	Good	●
Motor Condition	Good	●
Range Performance	As Expected	●
Battery Management	Good	●
Regenerative Braking	Working	●

ELECTRICAL INSPECTION

100/100

ELECTRICAL

Component	Condition	Status
Abs	Good	●
Horn	Working	●
Airbags	Good	●
Battery	Good	●
Indicators	Working	●
Lh Fog Lamp	Good	●



lh fog lamp

Rh Fog Lamp

Good



rh fog lamp

Ac Condition	Good	●
Lh Head Light	Good	●
		
Lh head light		
Rh Head Light	Good	●
 		
rh head light	rh head light	
Total Airbags	6	●
Reverse Camera	Good	●
Parking Sensors	Good	●
Electrical Comments	All Good	●



ROAD TEST INSPECTION

100/100

ROAD TEST

Component	Condition	Status
Brakes	Good	●
Steering	Good	●
Suspension	Good	●
Drive Shaft	Good	●
Transmission	Good	●
Abnormal Noises	None	●



ASSESSMENT SUMMARY

Exterior	100
Interior	100
Engine	100
Electrical	100
Road Test	100

Minor Issues

Front rh door panel gap

Inspector Signature: _____

Inspector: N. SAI KUMAR

360 Degrees Car Inspection | Professional Vehicle Assessment
This report is valid for 7 days from the date of generation. Report ID: 46b59250
Contact: +91 7207910711 | Powered by Dvaarik AI Web Agency