

360° Car Inspection Report

Professional Vehicle Assessment



Report ID: 5b770c1b

Date: 2026-04-17

Inspector: Sai



BUY

Exterior

100

Interior

100

Engine

100

Electrical

100

Road Test

100

EXTERIOR INSPECTION

100/100

EXTERIOR — FRONT



car front view photo

| Component | Condition | Status |
|-----------|-----------|--------|
| Bonnet | Good | ● |
| Lh Apron | Good | ● |



lh apron

Rh Apron

Good



rh apron

Fire Wall

Good



fire wall

Windshield

Good



windshield

Front Bumper

Good



front bumper

Front Grille

Good



front grille

Lh Leg Member

Good



lh leg member

Rh Leg Member

Good



rh leg member

Lower Cross Member

Good



Upper Cross Member

Good



upper cross member

EXTERIOR — RIGHT SIDE



car right view photo

| Component | Condition | Status |
|-----------|-----------|--------|
| Fender | Good | ● |



fender

| | | |
|----------|------|---|
| A Pillar | Good | ● |
|----------|------|---|



a pillar

B Pillar

Good



b pillar

C Pillar

Good



c pillar

Rear Door

Good



rear door

Rear Tyre

80%-100%



rear tyre

Front Door

Good



front door

Front Tyre

80%-100%



front tyre

Orvm Mirror

Good



orvm mirror

Quarter Panel

Good



quarter panel

Running Board

Good



running board

EXTERIOR — LEFT SIDE



car left view photo

| Component | Condition | Status |
|-----------|-----------|--------|
| Fender | Good | ● |



fender

| | | |
|----------|------|---|
| A Pillar | Good | ● |
|----------|------|---|



a pillar

B Pillar

Good



b pillar

C Pillar

Good



c pillar

Rear Door

Good



rear door

Rear Tyre

80%-100%



rear tyre

Front Door

Good



front door

Spare Tyre

80%-100%



spare tyre

Orvm Mirror

Good



orvm mirror

Quarter Panel

Good



quarter panel

Running Board

Good



EXTERIOR — REAR



dicky open photo

| Component | Condition | Status |
|------------|-----------|--------|
| Boot Floor | Good | ● |



boot floor

| | | |
|------------|------|---|
| Dicky Door | Good | ● |
|------------|------|---|



dicky door

| | | |
|------------|------|---|
| Rear Glass | Good | ● |
|------------|------|---|

Spare Tyre

80%-100%



spare tyre

Rear Bumper

Good



rear bumper

Tail Light Lh

Good



tail light lh



tail light rh



PAINT THICKNESS

| Panel | Microns | Assessment |
|---------------|-------------------|----------------|
| Hood | 101 µm | Original Paint |
| Roof | 105 µm | Original Paint |
| Photos | N/A | - |
| Boot Lid | 105 µm | Original Paint |
| Rear Bumper | 100 µm | Original Paint |
| Front Bumper | 100 µm | Original Paint |
| Lh Rear Door | 105 µm | Original Paint |
| Rh Rear Door | 102 µm | Original Paint |
| Lh Front Door | 104 µm | Original Paint |
| Rh Front Door | 102 µm | Original Paint |

UNDERBODY

| Component | Condition | Status |
|-----------|-----------|--------|
| Chassis | Good | ● |
| Floor Pan | Good | ● |
| Fuel Tank | Good | ● |



fuel tank

Exhaust Pipe

Good



exhaust pipe

INTERIOR INSPECTION

100/100

INTERIOR



dashboard photo

| Component | Condition | Status |
|-----------|-----------|--------|
| Ac Smell | Normal | ● |
| Speakers | Working | ● |
| Sun Roof | Good | ● |



sun roof

| | | |
|-----------|------|---|
| Dashboard | Good | ● |
| Gear Knob | Good | ● |

| | | |
|------------|-----------|---|
| Handbrake | Working | ● |
| Ac Cooling | Excellent | ● |
| Door Trims | Good | ● |
| Rear Seats | Good | ● |



rear seats

| | | |
|-------------|------|---|
| Driver Seat | Good | ● |
|-------------|------|---|



driver seat

| | | |
|-------------|----------|---|
| Roof Lining | Good | ● |
| Speedometer | Accurate | ● |

Infotainment

Working



infotainment

Passenger Seat

Good



passenger seat

Reverse Camera

Working



Steering Wheel

Good



Warning Lights

Yes



Instrument Cluster

Working



instrument cluster

ENGINE INSPECTION

100/100

ENGINE



engine photo

| Component | Condition | Status |
|-----------|-----------|--------|
| Sump | Good | ● |
| Turbo | Good | ● |
| Injector | Good | ● |



injector

Radiator

Good



radiator

Engine Oil

Clean



engine oil

Timing Belt

Good



Coolant Color

Green/Normal



Coolant Level

Full



coolant level

Engine Condition

Good



Engine Oil Level

Full



Video: video [Watch Video](#)



ELECTRICAL INSPECTION

100/100

ELECTRICAL

| Component | Condition | Status |
|---------------------|-----------|--------|
| Abs | Good | ● |
| Horn | Working | ● |
| Airbags | Good | ● |
| Battery | Good | ● |
| Indicators | Working | ● |
| Lh Fog Lamp | Good | ● |
| Rh Fog Lamp | Good | ● |
| Ac Condition | Good | ● |
| Lh Head Light | Good | ● |
| Rh Head Light | Good | ● |
| Total Airbags | 6 | ● |
| Reverse Camera | Good | ● |
| Parking Sensors | Good | ● |
| Electrical Comments | All Good | ● |



ROAD TEST INSPECTION

100/100

ROAD TEST

| Component | Condition | Status |
|--------------|-----------|--------|
| Brakes | Good | ● |
| Clutch | Good | ● |
| Steering | Good | ● |
| Suspension | Good | ● |
| Drive Shaft | Good | ● |
| Transmission | Good | ● |



ASSESSMENT SUMMARY

| | |
|------------|-----|
| Exterior | 100 |
| Interior | 100 |
| Engine | 100 |
| Electrical | 100 |
| Road Test | 100 |

Inspector Signature: _____

Inspector: Sai

360 Degrees Car Inspection | Professional Vehicle Assessment
This report is valid for 7 days from the date of generation. Report ID: 5b770c1b
Powered by Dvaarik AI Web Agency