

360° Car Inspection Report

Professional Vehicle Assessment



Report ID: e52a873a

Date: 2026-08-26

Inspector: N. SAI KUMAR



BUY

Exterior

99

Interior

100

Engine

100

Electrical

100

Road Test

89

EXTERIOR INSPECTION

99/100

EXTERIOR — FRONT



car front view photo

Component	Condition	Status
Bonnet	Good	●



bonnet



bonnet

Lh Apron

Good



lh apron

Rh Apron

Good



rh apron

Fire Wall

Good



fire wall

Windshield

Good



windshield

Front Bumper

Good



front bumper



front bumper

Front Grille

Good



front grille

Lh Leg Member

Good



lh leg member

Rh Leg Member


Good



rh leg member

Lower Cross Member

Good



lower cross member



upper cross member

EXTERIOR — LEFT SIDE



car left view photo

Component	Condition	Status
-----------	-----------	--------

Fender

Good



fender



fender

A Pillar

Good



a pillar



a pillar

B Pillar

Good



b pillar



b pillar

C Pillar

Good



c pillar



c pillar

Rear Door

Good



rear door



rear door



rear door

Front Door

Good



front door



front door



front door

Rear Tyre

80%-100%



rear tyre



rear tyre

Spare Tyre

80%-100%



spare tyre



spare tyre

Orvm Mirror

Good



orvm mirror

Quarter Panel

Good



quarter panel



quarter panel



quarter panel

Running Board

Good



running board

EXTERIOR — REAR



car dicky open photo



car rear view photo

Component	Condition	Status
-----------	-----------	--------



boot floor



boot floor



boot floor



dicky door




dicky door



dicky door



dicky door



rear glass

Spare Tyre

80%-100%



spare tyre

Rear Bumper

Good



rear bumper



rear bumper

Tail Light Lh

Good



tail light lh



tail light lh



tail light rh



tail light rh

EXTERIOR — RIGHT SIDE



car right view photo

Component	Condition	Status
-----------	-----------	--------

Fender

Good



fender



fender

A Pillar

Good



a pillar



a pillar

B Pillar

Good



b pillar



b pillar

C Pillar

Good



c pillar



c pillar

Rear Door

Good



rear door



rear door

Rear Tyre

80%-100%



rear tyre



rear tyre

Front Door

Good



front door



front door

Front Tyre

80%-100%



front tyre



front tyre

Orvm Mirror

Good



orvm mirror

Quarter Panel

Good



quarter panel



quarter panel



quarter panel

Running Board

Good



running board



PAINT THICKNESS


Panel	Microns	Assessment
Hood	N/A	-
Roof	N/A	-
Photos	N/A	-
Boot Lid	N/A	-
Rear Bumper	N/A	-
Front Bumper	N/A	-
Lh Rear Door	N/A	-
Rh Rear Door	N/A	-
Lh Front Door	N/A	-
Rh Front Door	N/A	-

UNDERBODY

Component	Condition	Status
Chassis	Good	●



chassis



chassis



chassis

Floor Pan

Good



floor pan



floor pan

Fuel Tank

Good





exhaust pipe



exhaust pipe



exhaust pipe



exhaust pipe



exhaust pipe

INTERIOR INSPECTION

100/100

INTERIOR



dashboard photo



dashboard photo

Component	Condition	Status
Ac Smell	Normal	

Sun Roof

Good



sun roof



sun roof

Dashboard

Good



dashboard

Gear Knob

Good



gear knob

Handbrake

Working



handbrake

Ac Cooling

Excellent



ac cooling

Door Trims

Good



door trims



door trims



door trims



door trims

Rear Seats

Good



rear seats

Driver Seat

Good



driver seat

Roof Lining

Good



roof lining



roof lining

Infotainment

Working



infotainment

Passenger Seat

Good



passenger seat



passenger seat

Reverse Camera

Working



reverse camera

Steering Wheel

Good



steering wheel

Warning Lights

Yes





instrument cluster

ENGINE INSPECTION

100/100

ENGINE



engine photo



engine photo

Component	Condition	Status
-----------	-----------	--------

Sump

Good




sump



sump

Radiator

Good



radiator

Engine Oil

Clean



engine oil

Timing Belt

Good



Coolant Color	Green/Normal	●
---------------	--------------	---



coolant color

Coolant Level	Full	●
---------------	------	---



coolant level

Engine Condition	Good	●
------------------	------	---

Engine Oil Level	Full	●
------------------	------	---



engine oil level

Video: video [Watch Video](#)

ELECTRICAL INSPECTION

100/100

ELECTRICAL

Component	Condition	Status
Abs	Good	●
Horn	Working	●
Airbags	Good	●
Battery	Good	●
Wiring	Good	●
Indicators	Working	●
Lh Fog Lamp	N/A	●
Rh Fog Lamp	N/A	●
Ac Condition	Good	●
Lh Head Light	Good	●



Lh head light

Power Windows

All Windows & Window Switchs Working



Rh Head Light	Good	●
		
rh head light		
Total Airbags	4	●
Parking Sensors	Good	●
Electrical Comments	All Good	●

ROAD TEST INSPECTION

89/100

ROAD TEST

Component	Condition	Status
Brakes	Good	●
Clutch	Good	●
Steering	Good	●
Suspension	Good	●
Drive Shaft	Good	●
Transmission	Gear Box Oil Leakage	●



transmission

Abnormal Noises

None

●



ASSESSMENT SUMMARY



Major Issues

Gear box side oil leakage

Inspector Signature: _____

Inspector: N. SAI KUMAR

360 Degrees Car Inspection | Professional Vehicle Assessment
This report is valid for 7 days from the date of generation. Report ID: e52a873a
Contact: +91 7207910711 | Powered by Dvaarik AI Web Agency