

360° Car Inspection Report

Professional Vehicle Assessment



Report ID: ca2f493f

Date: 2026-08-25

Inspector: N. SAI KUMAR



BUY

Exterior

76

Interior

100

Engine

100

Electrical

100

Road Test

94

EXTERIOR INSPECTION

76/100

EXTERIOR — FRONT



front view car photo

Component	Condition	Status
-----------	-----------	--------



roof



roof



roof

Bonnet

Scratch



bonnet



bonnet



bonnet

Clow Top

Good



clow top

Lh Apron


Good



lh apron

Rh Apron

Good



rh apron

Fire Wall

Good



fire wall

Windshield

Good



windshield

Front Bumper

Repaint



front bumper



front bumper

Front Grille

Good



front grille

Lh Leg Member


Good



lh leg member

Rh Leg Member

Good



rh leg member

Lower Cross Member

Good



lower cross member



upper cross member

EXTERIOR — LEFT SIDE



left side view car photo

Component	Condition	Status
-----------	-----------	--------



fender



fender



a pillar



a pillar



a pillar



b pillar



b pillar



b pillar

C Pillar

Good



c pillar



c pillar



c pillar

Rear Door

Repaint



rear door



rear door

Front Door

Repaint



front door



front door

Door Gap Lh

Uniform



Orvm Mirror

Good



orvm mirror



quarter panel



quarter panel



quarter panel

Running Board

Good



running board

EXTERIOR — REAR



dicky open photo



rear view car photo

Component	Condition	Status
-----------	-----------	--------



boot floor



boot floor



boot floor



boot floor



boot floor

Dicky Door

Scratches



dicky door



dicky door



dicky door

Rear Glass

Good



rear glass



rear glass

Spare Tyre

60%-80%



Rear Bumper

Repaint



rear bumper



rear bumper

Tail Light Lh

Cracked



tail light lh



tail light lh

Tail Light Rh

Cracked



tail light rh



tail light rh

EXTERIOR — RIGHT SIDE



right side view car photo

Component	Condition	Status
Fender	Repaint	



fender



fender

A Pillar

Good



a pillar



a pillar




a pillar

B Pillar

Good



b pillar



b pillar



c pillar



c pillar



c pillar

Rear Door

Repaint



rear door



rear door



rear door



rear door

Rear Tyre

35%-46%



Front Door

Repaint



front door



front door

Front Tyre

Worn out



front tyre

Orvm Mirror

Scratches



orvm mirror



quarter panel



quarter panel



quarter panel



running board



running board



PAINT THICKNESS

Panel	Microns	Assessment
Hood	N/A	-
Roof	N/A	-
Photos	N/A	-
Boot Lid	N/A	-
Rear Bumper	N/A	-
Front Bumper	N/A	-
Lh Rear Door	N/A	-
Rh Rear Door	N/A	-
Lh Front Door	N/A	-
Rh Front Door	N/A	-



UNDERBODY

Component	Condition	Status
-----------	-----------	--------

Floor Pan

Good



floor pan



floor pan



floor pan



floor pan



floor pan

Fuel Tank

Good



Exhaust Pipe

Good



exhaust pipe

Flood Damage

None



INTERIOR INSPECTION

100/100

INTERIOR



dashboard photo



dashboard photo



dashboard photo



dashboard photo

Component	Condition	Status
Carpet	Good	●
Ac Smell	Normal	●

Sun Roof

Good



sun roof



sun roof

Dashboard

Good



Handbrake

Working



Ac Cooling

Excellent



ac cooling

Door Trims

Good



Rear Seats

Good



rear seats

Driver Seat

Good



driver seat



driver seat

Flood Signs

None



Roof Lining

Good



Speedometer

Accurate



Infotainment

Working



infotainment

Passenger Seat

Good



passenger seat



passenger seat

Reverse Camera	Working	●
----------------	---------	---



reverse camera

Steering Wheel	Good	●
----------------	------	---



steering wheel

Warning Lights	Yes	●
----------------	-----	---

Instrument Cluster	Working	●
--------------------	---------	---



instrument cluster

ENGINE INSPECTION

100/100

ENGINE



engine photo




engine photo



engine photo



engine photo



engine photo

Component	Condition	Status
-----------	-----------	--------

Sump

Good



sump



sump

Radiator

Good



radiator



radiator

Engine Oil

Clean



engine oil

Timing Belt

Good



Coolant Color

Green/Normal



Coolant Level

Full



coolant level

Exhaust Smoke

No Smoke



Engine Condition

Good



Engine Oil Level

Full



Video: video [Watch Video](#)

ELECTRICAL INSPECTION

100/100

ELECTRICAL

Component	Condition	Status
Abs	Good	●
Horn	Working	●
Airbags	Good	●
Battery	Good	●
Indicators	Working	●
Lh Fog Lamp	Good	●



lh fog lamp

Rh Fog Lamp

Good



rh fog lamp

Ac Condition	Good	●
Lh Head Light	Good	●
  lh head light lh head light		
Rh Head Light	Good	●
  rh head light rh head light		
Total Airbags	6	●
Reverse Camera	Good	●
Parking Sensors	Good	●



ROAD TEST INSPECTION

94/100

ROAD TEST

Component	Condition	Status
Brakes	Good	●
Clutch	Hard	●
Steering	Good	●
Distance	4	●
Stability	Good	●
Suspension	Good	●
Drive Shaft	Good	●
Transmission	Good	●
Engine Pickup	Good	●
Abnormal Noises	None	●



ASSESSMENT SUMMARY



Minor Issues

Clutch hard
Gear shifting hard
Need to replace all tyres

Inspector Signature: _____

Inspector: N. SAI KUMAR

360 Degrees Car Inspection | Professional Vehicle Assessment
This report is valid for 7 days from the date of generation. Report ID: ca2f493f
Contact: +91 7207910711 | Powered by Dvaarik AI Web Agency